



## 942-111 POWER DISTRIBUTION BLOCK MOUNTING INSTRUCTIONS



## NOTE:

- Mount Power Distribution Block in a location central to the switch machines you wish to connect.
- Mount to benchwork using screws and spacers supplied. Drill pilot holes using #43 bit (from 942-140 Drill Set) if needed.



For additional connection information see the Switch Machine Reference Guide at walthers.com/products/walthers-control-system.