



HO Structure Kit

OLD TIME COAL CONVEYOR (3-PACK)

933-3520


Thanks for purchasing this Cornerstone Series® Kit!
Please read all instructions before starting. All parts are molded in styrene plastic, so use glues and paints which are compatible.

Before Assembly

Check kit for proper number of parts. Cut and file flash from parts. Sand edges to ensure right angle joints with no gaps between parts.


LARGE CONVEYOR

1. Glue the conveyor sides (61,62) to the belt (60). Glue the motor box (66) underneath the belt in between the little knobs on the bottoms of the sides. Glue the chute (63) onto the conveyor assembly.
2. Slide the conveyor assembly through the top of the upright (65) and glue it to the middle horizontal bar. Glue the bottom brace (64) to the upright as well as to the bottom of the conveyor.
3. Glue the wheels (67) to the upright.



SMALL CONVEYOR

1. Bend up the end of the unloader belt (68), at the groove underneath, and glue to the ridges on the insides of the sides (69,70). Glue the motor box (71) in front of the nubs on the top of the sides.
2. Glue the wheels (67) onto the sides.



Painting

You can paint this kit with brush, spray can or airbrush. Paint after assembly is complete to help cover up any seams. Weathering is optional.